"SNAFU", the 6th.!!!!!:

SUB MARINE CONSULTING

Ratio Toolbox 1.8.2



RATIO

COMPUTERS

Willkommen beim Ratio® Computer-Toolkit zum Einrichten und Warten Ihres Tauchcomputers.

Schließen Sie einen Gerät mit dem Ratio® USB-Kabel an den PC an dann gehen Sie auf "PC Mode" und drücken Sie die Taste "Verbinden".

Toolbox 1.8.2



Ratio® iX3M GPS DEEP

Firmware 4.0.74/016 (Deutsch) Seriennr. 003179

Verbunden mit COM6

Bitte wählen Sie die Operation, die auf diesem G

RATIO IX3M DEEP:

after update to the latest Software Version: 4.0.74 / 016 in 07 / 2021 via the latest RATIO Toolbox 1.8.2

"SNAFU", the 6th.!!!!!:

SUB MARINE CONSULTING



RATIO IX3M DEEP: ERR 01 NICHT TAUCHEN

reads in english: DO NOT DIVE !!!

"SNAFU", the 6th.!!!!!!:

SUB MARINE CONSULTING



And, the next result (PLANER NICHT VORHANDEN) reads in english: "OC DIVE PLANNER NOT AVAILABLE!"

"SNAFU", the 6th.!!!!!!:

SUB MARINE CONSULTING

99%
O.Om BUL
O:00
NICHT
TAUCHEN!

MIX PP02 6 21% 8.28



And, the next results from the Log-Book, as well in english: "Do NOT Dive!" If the compass error is related to the new firmware is as of this writing (July 2021) not really clear!

"SNAFU", the 6th.!!!!!!


SUB MARINE CONSULTING



After the update, then the box decided by itself to:

- → periodically switch on (no user intervention)
- → freezes the display in grey
- → switches off, and
- → de-activates the 4 push-buttons!
- → So this required a:
- → complete battery run-down via "PC Mode" to reset the piezo-sensor!
- → and another full re-charging cycle there after

SUB MARINE CONSULTING





Ratio® iX3M GPS DEEP

Firmware 4.0.77/016 (Deutsch)
Seriennr. 003179
Verbunden mit COM6

Bitte wäh soll.



SNAFU, the 6th.: continued!

after update to the next latest Software Version: 4.0.77.22 / 016 in 20.09.2021

via the latest RATIO Toolbox 1.8.2 →

SUB MARINE CONSULTING

4.0.77.22 / 016 20.09.2021 →



- → with a pressure reading of 700 mBar somewhat out in the left field
- → (the altitude with 3.3 km also ...)
- → the correct ambient pressure on my desk would have been
- → ca. 993 mBar + / 2 mBar (and no water around ...)
- → very shortly thereafter:
- → the box displayed "reset" (in red), then:
- → "Kalibrierung" (in <u>yellow</u>, this reads: "calibration"), then:

SUB MARINE CONSULTING

4.0.77.22 / 016 20.09.2021:

- → then it jumped directly into dive mode @ ca. 2.8 m
- → which required the next battery run-down!



SUB MARINE CONSULTING

The pressure / depth reading obviously dependant from the voltage:





SUB MARINE CONSULTING

→ the run-down from 95 % to 0 % took approx. 18 h:



→ the leading 1 for ca. 1,068 min run-time is missing though, sometimes ...



→ 1 h later, still @ 0 %, but by now we have the leading 1 ...



SUB MARINE CONSULTING

→ @ 0 % it jumped back in time to where the whole rigmarole started, with the usual "GEWEBERESET" (tissue reset):



→ it then featured again the "grey, blank":



→ and, after a creative trough, started this loop again for about 4 minutes, then the battery was completely dead. By recharging it looked like that, without a pressure reading:



SUB MARINE CONSULTING



SNAFU, the 6th.: continued!

after update to the next latest Software Version: 4.0.78 / / 016 in 04.10.2021

via the latest RATIO Toolbox 1.8.2 ->

"SNAFU", the 6th.: con't. 4.0.78.1 / 016 in 04.10.2021

After the usual battery run-down & pressure reset: the results still not convincing >


SUB MARINE **CONSULTING**





SUB MARINE CONSULTING

4.0.78.1 / 016 during test dive: the results still not convincing → after 24 min. into the test-dive, the box decided to freak out: @3 m depth, it jumped into surface-mode:



i.e.: dive time = 0, depth = 0 & tissue reset (,,GEWEBERESET", red display)

SUB MARINE CONSULTING

4.0.78.1 / 016 during test dive: the results still not convincing → then, after 53 min. into the test-dive, the box featured a stylish "TEC" display (just plain black ...) ☺



4.0.78.1 / 016 the results still not convincing →

then, at times, during SI, the box decides by itself to get a calibration =

KALIBRIERUNG:

The topical updates from 4.0.74 to 4.0.78.1 rendered the compass as well useless:








4.0.78.1 / 016 the results still not convincing → the topical

updates from 4.0.74 to 4.0.78.1 rendered the log-book as well useless:

Some times, for e.g. @ # 44, 45 & 46, it worked, just a little bit ...



P1080487.JPG



P1080490.JPG



LOGBUCH
N 39 83:25 21.89.21

LZ:
HAX:
ZNS:
OTU:
HODUS:
TEHP:
HIX:
R A T I O

P1080488.JPG



P1080491.JPG




SUB MARINE CONSULTING



P1080489.JPG



P1080492.JPG



"SNAFU", the 6th.: and the END!!!

SUB MARINE CONSULTING

Version:	per:
	poi.
4.0.78.1 / 016	04.10.2021
4.0.77.22 / 016	20.09.2021
4.0.74 / 016	13.07.2021
4.0.72 / 015	19.06.2020
4.0.70 / 014	20.01.2020
4.0.68 / 013	24.06.2019
4.0.66 / 013	25.05.2019
4.0.64 / 013	Mai 19
4.0.58 / 013	Mrz 19
4.0.54 / 013	Dez 18
4.0.50 / 013	Okt 18
4.0.46 / 013	Sep 18
4.0.44 / 013	Jun 18
4.0.40 / 013	Jan 18
4.0.26 / 013 -	-
4.0.20 / 011 -	-
4.0.10 / 011	Mai 17
3.3.4 / 010	2017
3.3.0 / 009	2016

Since 2016 we've tested 19 Versions / updates! →

Thus we have now a relatively rare combination of electro-mechanical junk and shoddy, meshugge software. This box is, after all these 19 updates and tests during 2016 to 2021 assessed as nebech [1], i.e.: completely useless for diving!

So it is banished to an appropriate place in our little virtual Dive Computer Museum:

https://www.divetable.info/museum_g.htm

https://www.divetable.info/museum_e.htm

with all the other junk we've been testing and collecting during the last 35 years, and: never to be used again underwater!

For explanation of nebech: [1] Ulam, S. M. (1991) Adventures of a Mathematician; p. 194 - 195