




2023, Part I: PERDIX update

Perdix AI with old firmware, version V87:



Perdix AI connected with Bluetooth to PC,
and Shearwater PC app connected with
Shearwater portal:




2023, Part I: PERDIX update

Transmission of new firmware from PC via Bluetooth to dive computer
(very slow ..., and error prone):



Final message from PC app:




2023, Part I: PERDIX update

and the result of the 1st. run:



2023, Part I: PERDIX update

After ignoring a hand-ful of erratic error messages
(mobile data active?, WLAN activated?, etc ... pp)
after the 4th. run:



Firmware Update

Update SUCCESS



Decompression
Tissues Cleared

Plan repetitive
dives accordingly

Continue

System Info

Serial #:	201370DF
Features:	20090
Firmware:	v93/BT10
Hardware:	SA-02A